



Mercedes-Benz









Vehicle model	SPRINTER 224 / 324 / 424 / 524 Petrol 224 / 324 / 424 / 524 GLP		SPRINTER 224 / 324 / 424 / 524 Petrol 224 / 324 / 424 / 524 GLP		VARIO 613D / 616D / 618D 813D / 816D / 818D		ATEGO		ATEGO			
Year	(09/2008>)		(09/2008>)		(1997>)		(2014>)		(2014>)			
Engine Type	M 272 E 35 (Euro 4-5-6)		M 272 E 35 (Euro 4-5-6)		OM 904 LA (Euro 4-5)		OM934 (Euro 6)		OM934 (Euro 6)			
CV(kW) @ rpm	258 (190) @ 5.900		258 (190) @ 5.900		156 (115) @ 2.200		156 (115) @ 2.200 177 (130) @ 2.200 211 (155) @ 2.200 231 (170) @ 2.200		156 (115) @ 2.200 177 (130) @ 2.200 211 (155) @ 2.200 231 (170) @ 2.200			
N. of cylinders/cm3	6 / 3.498		6 / 3.498		4 / 4.249		4 / 5.132		4 / 5.132			
Volts	12		12		24		24		24			
Air Conditioning	Vehicles with or without A/C		Vehicles with or without A/C		Only Vehicles without A/C		Vehicles with or without A/C		Vehicles with or without A/C			
Recommended fittings	Suction		Discharge		Suction		Discharge		Suction		Discharge	
Compressors type	TM 21		SD5H09 (ref.5074)		TM 21		TM 21		TM 21 QP 21			
Comments	- When vehicle is not equipped with the crankshaft pulley N87, request code P/N 1111008032. - Can be fit in right hand drive vehicles.		- When vehicle is not equipped with the crankshaft pulley N87, request code P/N 1111008032 - Can be fit in right hand drive vehicles.		- Can be fit in right hand drive vehicles		- Can be fit in right hand drive vehicles - Fittings not included in the kit - FOR VEHICLES EQUIPPED WITH THE N7C OPTION		- Can be fit in right hand drive vehicles - Fittings not included in the kit			
Clutch type	Without clutch pulley		Without clutch pulley		Without clutch pulley		Without clutch pulley		With clutch pulley		Without clutch pulley	
	Poly-V 8K Ø137 5.512 rpm		Poly-V 5K Ø119 6.200 rpm		Poly-V 8K Ø137 3.206 rpm		8K Ø137 4.100 rpm		8K Ø137 4.100 rpm		2A Ø145 3.820 rpm	
Kit No.	KB11078032		KB14088062		KB10028014		KB14078061		KB14078061E		KB15078076	
Last update	2011-12-22		2014-09-08		2010-02-12		2015-07-17		2015-09-03			



Mercedes-Benz



Vehicle model	ATEGO		ATEGO		ATEGO		ATEGO - Euro 3 / Euro 4 / Euro 5	
Year	(2014>)		(2014>)		(2014>)		(1998>)	
Engine Type	OM934 (Euro 6)		OM936 (Euro 6)		OM936 (Euro 6)		OM 904 LA (Euro 3-4-5) OM 924 LA (Euro 3-4-5)	
CV(kW) @ rpm	156 (115) @ 2.200 177 (130) @ 2.200 211 (155) @ 2.200 231 (170) @ 2.200		238 (175) @ 2.200 272 (200) @ 2.200 299 (220) @ 2.200		238 (175) @ 2.200 272 (200) @ 2.200 299 (220) @ 2.200		122 (90) / 129 (95) / 156 (115) / 177 (130) / 150 (110) @ 2.200 218 (160) @ 2.200	
N. of cylinders/cm3	4 / 5.132		6 / 7.700		6 / 7.700		4 / 4.249 4 / 4.800	
Volts	24		24		24		24	
Air Conditioning	Vehicles with or without A/C		Vehicles with or without A/C		Vehicles with or without A/C		Vehicles with or without A/C	
Recommended fittings	Suction	Discharge	Suction	Discharge	Suction	Discharge	Suction	Discharge
								
Compressors type	TM 31		TM 21 QP 21		TM 31		TM 31	
Comments	- Can be fit in right hand drive vehicles - Fittings not included in the kit - FOR VEHICLES EQUIPPED WITH THE N7C OPTION		- Can be fit in right hand drive vehicles - Fittings not included in the kit - This kit is not suitable for vehicles with the option N7.		- Can be fit in right hand drive vehicles - Fittings not included in the kit - FOR VEHICLES EQUIPPED WITH THE N7C OPTION		- Can be fit in right hand drive vehicles. - Fittings supplied with unit.	
Clutch type	Without clutch pulley		Without clutch pulley		Without clutch pulley		Without clutch pulley	
	8K Ø151 3.730 rpm		2A Ø145 3.520 rpm		8K Ø151 3.730 rpm		2B Ø158 4.000 rpm	
Kit No.	KB14058058		KB16098082		KB14038057		KB12048041	
Last update	2015-07-17		2016-12-16		2015-07-17		2012-05-18	



Mercedes-Benz



Vehicle model	ATEGO - Euro 3 / Euro 4 / Euro 5		ATEGO - Euro 3 / Euro 4 / Euro 5		ATEGO - Euro 3 / Euro 4 / Euro 5	
Year	(1998>)		(1998>)		(1998>)	
Engine Type	OM 904 LA (Euro 3-4-5) OM 924 LA (Euro 3-4-5)		OM 906 LA (Euro 3-4-5)		OM 906 LA (Euro 3-4-5)	
CV(kW) @ rpm	122 (90) / 129 (95) / 156 (115) / 177 (130) / 150 (110) @ 2.200 218 (160) @ 2.200		231 (170) / 238 (175) / 256 (188) / 279 (205) / 286 (210) @ 2.200		231 (170) / 238 (175) / 256 (188) / 279 (205) / 286 (210) @ 2.200	
N. of cylinders/cm3	4 / 4.249 4 / 4.800		6 / 6.374		6 / 6.374	
Volts	24		24		24	
Air Conditioning	Only Vehicles without A/C		Vehicles with or without A/C		Only Vehicles without A/C	
Recommended fittings	<i>Suction</i>	<i>Discharge</i>	<i>Suction</i>	<i>Discharge</i>	<i>Suction</i>	<i>Discharge</i>
Compressors type	TM 31		TM 31		TM 31	
Comments	- Can be fit in right hand drive vehicles. - Fittings supplied with unit.		- Can be fit in right hand drive vehicles. - Fittings supplied with unit.		- Can be fit in right hand drive vehicles. - Fittings supplied with unit.	
Clutch type	Without clutch pulley		Without clutch pulley		Without clutch pulley	
	2B Ø158 3.899 rpm		2B Ø158 4.000 rpm		2B Ø158 3.899 rpm	
Kit No.	KB10038018		KB12048041		KB10038018	
Last update	2012-04-11		2012-05-18		2012-04-11	



Mercedes-Benz



Vehicle model	INTOURO E / M / ME	CHASSIS OC 500 RF (Euro 6)	MERCEDES OC 500 RF (Euro 6) 1939 / 1943 / 2543			
Year	---	(2014>)	(10>2014)			
Engine Type	OM 926 LA 210	OM936 (Euro 6)	OM470 (Euro 6)			
CV(kW) @ rpm	282 (207) @ 2.200	238 (175) @ 2.200 272 (200) @ 2.200 299 (220) @ 2.200	394 (290) @ 1.800 428 (315) @ 1.800			
N. of cylinders/cm3	6 / 7.200	6 / 7.700	6 / 10.676			
Volts	24	24	24			
Air Conditioning	Vehicles with or without A/C	Only Vehicles without A/C	Only Vehicles without A/C			
Recommended fittings	Suction	Discharge	Suction	Discharge	Suction	Discharge
Compressors type	X430	BOCK FK40	BOCK FK40			
Comments	- Can be fit in right hand drive vehicles. - Fittings supplied with unit.	- Can be fit in right hand drive vehicles. - Fittings not included in the kit.	- COMPRESSOR PULLEY LINNING LA16_0234Y - Vehicle equipped with original option HK85 - Fixing for 3rd alternator reference Mercedes A 000 150 72 12			
Clutch type	Without clutch pulley	Without clutch pulley	Without clutch pulley			
	2B Ø204 2.426 rpm	2B Ø203 2.746 rpm	2B Ø203 / 2A Ø254 2.730 rpm			
Kit No.	KB11118035X	KB14098064	KB15028072			
Last update	2012-05-14	2015-02-05	2015-03-18			